

Brand på en kemikalieanläggning.

961122

Extremt kortfattad

Brand uppstod i det gasfyllda utrymmet ovanför en svavelsmälta i en tank. Den tändande gnistan är inte identifierad. Branden släcktes med hjälp av vatten. Bildad svaveldioxid skingrades med hjälp av vattengardiner.

Inblandade ämnen och mängder

	CAS Nr.	Mängd
svavel	7704-34-9	okänt
svaveldioxid	7446-09-5	okänt

Skador:

Människor: Inga personskador.
Materiella: Inga skador.
Miljö/ekologi: Inga effekter rapporterade.
Infrastruktur: Inga effekter.

Erfarenheter redovisade (Ja/Nej): Nej

Report Profile

Identification of Report:

country: FA ident key: 1800_091_01

reported under Seveso I directive as major accident reports: SHORT

Date of Major Occurrence: Time of Major Occurrence

start: 22/11/1996 start:

finish: 22/11/1996 finish:

Establishment:

name:

address:

industry: 2001 general chemicals manufacture

Seveso II status: not applicable: Yes art. 6 (notification): No

art. 7 (MAPP): No

art. 9 (safety report): No

Date of Report:

short: full:

Authority Reporting:

name:

address:

Authority Contact:

rep_cont_name:

rep_cont_phone:

rep_cont_fax:

Additional Comments:

a) - not applicable -

b) - not applicable -

c) - not applicable -

d) - not applicable -

e) - not applicable -

Short Report

country: FA ident key: 1800_091_01

Accident Types:

release: No explosion: No

water contamination: No other: No

fire: Yes

description:

fire of the gaseous roof of a of tank containing molten sulphur.

Substance(s) Directly Involved:

toxic: No explosive: No

ecotoxic: No other: No

flammable: Yes

description:

molten sulphur

Immediate Sources of Accident:

storage: Yes transfer: No

process: No other: No

description:

the actual ignition source is unknown

Suspected Causes:

plant or equipment: No environmental: No

human: No other: Yes

description:

the causes are unknown

Immediate Effects:

material loss: No

human deaths: No

human injuries: No community disruption: No

other: Yes

ecological harm: No

national heritage loss: No

description:

the fire caused some SO2 emissions. No victims and no environmental impact.

Emergency Measures taken:

on-site systems: Yes **decontamination:** No

external services: No **restoration:** No

sheltering: No **other:** No

evacuation: No

description:

the internal fire was extinguished by the injection of water vapour. The SO2 waste gases were abated with water curtains.

Immediate Lessons Learned:

prevention: No **other:** Yes

mitigation: No

description:

no information given.