# Explosion i ett slakthus.

941208 Extremt kortfattad

En kokare på 2,8 m3 som arbetade vid 10 bars tryck exploderade och dödade tre personer. Delar av kokaren slungades 150 meter bort.

# Inblandade ämnen och mängder

CAS Nr. Mängd

vattenånga

Skador:

Människor: Tre personer omkom.

Materiella: Inga detaljer rapporterade.

Miljö/ekologi: Inga effekter rapporterade.

Infrastruktur: Inga effekter rapporterade.

Erfarenheter redovisade (Ja/Nej): Nej

# **Report Profile**

# **Identification of Report:**

country: FA ident key: 1800 121 01

reported under Seveso I directive as major accident reports: SHORT+FULL

Date of Major Occurrence: Time of Major Occurrence

start: 08/12/1994 start: 08:15:00

finish: 08/12/1994 finish:

# **Establishment:**

name:

address:

industry: 2019 food and drink

meat production factory (butchery)

Seveso II status: not applicable: Yes art. 6 (notification): No

art. 7 (MAPP): No

art. 9 (safety report): No

### **Date of Report:**

short: full:

# **Authority Reporting:**

name:

address:

# **Authority Contact:**

rep\_cont\_name:

rep\_cont\_phone:

rep\_cont\_fax:

# **Additional Comments:** a) - not applicable b) - not applicable c) - not applicable d) - not applicable e) - not applicable -**Short Report country:** FA **ident key:** 1800\_121\_01 **Accident Types:** release: No explosion: Yes water contamination: No other: No fire: No description: boiler explosion resulting in three fatalities. **Substance(s) Directly Involved:** toxic: No explosive: No ecotoxic: No other: Yes flammable: No description: water /vapour **Immediate Sources of Accident:** storage: No transfer: No process: Yes other: No description: explosion of a boiler **Suspected Causes:** plant or equipment: No environmental: No human: No other: Yes description: no information is given **Immediate Effects:** material loss: Yes human deaths: Yes human injuries: No community disruption: Yes other: No ecological harm: No national heritage loss: No

description:

### **Emergency Measures taken:**

on-site systems: Yes decontamination: No

external services: Yes restoration: No

sheltering: No other: Yes

evacuation: No

description:

no information is given

#### **Immediate Lessons Learned:**

prevention: No other: Yes

mitigation: No

description:

no information is given

# **A Occurrence Full Report**

**country:** FA **ident key:** 1800\_121\_01

## 1 Type of Accident

remarks: - not applicable -

## 2 Dangerous Substances

remarks: - not applicable -

#### 3 Source of Accident

illustration: a series of photographs showing the exploded boiler, detached parts and the

explosion site, a list of fragments of the boiler, a description of the

boiler and a 1/1650 map of the area in which the accident occurred

remarks: The accident occurred with an industrial boiler producing steam for 5

steamers (cookers). The boiler is made in the form of a cylindrical body

closed with 2 flat bases (lids). The boiler comprises a focus tube and  $24\,$ 

exhaust gas tubes. Its ... see Appendix Full Report A  $\slash$  source of accident -

remarks

# **4 Meteorological Conditions**

precipitation none: fog: rain: hail: snow:

No No No No No

wind speed (m/s):

direction (from):

stability (Pasquill):

ambient temperature ( $\infty$ C):

remarks: - not applicable -

# 5 Causes of Major Occurrence

main causes

```
technical / physical 5102 operation: component/machinery failure/malfunction
- not applicable -
- not applicable -
- not applicable -
- not applicable -
human / organizational - not applicable -
remarks: The supposed cause of the explosion is the drainage (dewatering) of the focus tube,
perhaps caused by the failure of the water feeding system. Other hardware related causes
might be possible as well.
6 Discussion about the Occurrence
- not applicable -
Type of Accident country: FA ident key: 1800_121_01
event:
major occurrence 1301 explosion: pressure burst (rupture of pressure system)
initiating event - not applicable -
associated event - not applicable -
Dangerous substances
country: FA ident key: 1800_121_01
a) total establishment inventory
CAS number: identity: water in form of steam
name from Seveso I Directive: - not applicable -
name from Seveso II Directive: - not applicable -
category from Seveso II: - not applicable -
other hazards (1): - not applicable -
other hazards (2): - not applicable -
maximum quantity (tonnes): 7
use of substance as: - not applicable -
b) substance belongs to relevant inventory directly involved: Yes
actual quantity: 7 potential quantity: -1
c) substance belongs to relevant inventory indirectly involved: No
{\bf actual\ quantity:}\ 0\ {\bf indir\_pot\_quant:}\ 0
Source of Accident - Situation country: FA ident key: 1800_121_01
situation
industry
inititating event - not applicable -
```

```
associated event - not applicable -
activity/unit
major occurrence 3106 process: power generation (burning fuel, etc.)
inititating event - not applicable -
associated event - not applicable -
component
major occurrence 4009 heat exchanger (boiler, refrigerator, heating coils, etc.)
inititating event - not applicable -
associated event - not applicable -
B Consequences Full Report
country: FA ident key: 1800_121_01
1 Area concerned
affected
extent of effects installation: Yes
establishment: Yes
off-site; local: Yes
off-site; regional: No
off-site; transboundary: No
illustration of effects the map shows the points in which the boiler and its fragments were
thrown... see Appendix Full Report B / area concerned - illustration of
effects
remarks the body of the boiler was thrown about 150 meters to the north, whereas the foc... see Appendix
Full Report B / area concerned - remarks
2 People
establishment popul. emergency personnel off-site population
total at risk -1 -1 -1
immediate fatalities 3 0 0
subsequent fatalities 0 0 0
hospitalizing injuries 0 0 0
other serious injuries 0\ 0\ 0
health monitoring 0\ 0\ 0
remarks - not applicable -
3 Ecological Harm
pollution/contamination/damage of:
- residential area (covered by toxic cloud) Yes
- common wild flora/fauna (death or elimination) No
```

- rare or protected flora/fauna (death or elimination) No

- water catchment areas and supplies for consumption or recreation  $\,No\,$ - land (with known potential for long term ecological harm or No preventing human access or activities) - marine or fresh water habitat No - areas of high conservation value or given special protection  $\,No\,$ remarks a nearby locksmith's shop is damaged 4 National Heritage Loss effects on: - historical sites None - historic monuments None - historic buildings None - art treasures None remarks - not applicable -**5 Material Loss** establishment losses off site losses costs (direct costs to operator) (social costs) in ECU FFR ECU FFR material losses -1 -1 -1 -1 response, clean up, restoration -1 -1 -1 -1 remarks - not applicable -6 Disruption of Community Life establishment/plant evacuated disabled/unoccupiable destroyed - nearby residences/hotels No No No - nearby factories/offices/small shops No Yes No - schools, hospitals, institutions No No No - other places of public assembly  $\ensuremath{\text{No}}$   $\ensuremath{\text{No}}$   $\ensuremath{\text{No}}$ interruption of utilities etc. no / yes duration - gas No - electricity Yes - water No - sewage treatment works No - telecommunications No - main roads No - railways No - waterways No - air transport No significant public concern none local level national level - off site populations No No No - media interest No No No

- political interest No No No

# 7 Discussion of Consequences

# **Ecological Components involved**

country: FA ident key: 1800\_121\_01
type: - not applicable threatened: not applicable affected: No

**C** Response Full Report **country:** FA **ident key:** 1800\_121\_01 1 Emergency Measures taken - on site - not applicable - - not applicable -- not applicable - - not applicable -- not applicable - - not applicable -- off site - not applicable - - not applicable -- not applicable - - not applicable -- not applicable - - not applicable still - on site - not applicable - - not applicable required - not applicable - - not applicable -- not applicable - - not applicable -- off site - not applicable - - not applicable -- not applicable - - not applicable -- not applicable - - not applicable continuing contamination or danger -on site not applicable -off site not applicable remarks - not applicable -2 Seveso II Duties pre-accident evaluation Article item not due yet not done done/submitted evaluated 6 notification No No No No 7 policy (MAPP) No No No No 9 safety report No No No No 9, 10, 11 update No No No No 11 internal plan No No No No 11 external plan No No No No

13 informing public No No No No

9, 12 siting policy No No No No

post-accident evaluation			
Seveso II duty was actual were actual compared with actual			
contingency consequences consequences, the			
addressed? addressed? predicted extent was?			
Article item			
7 policy (MAPP) not applicable not applicable			
9 current safety report not applicable not applicable not applicable			
11 internal plan not applicable not applicable			
11 external plan not applicable not applicable			
13 informing public not applicable not applicable not applicable			
9, 12 siting policy not applicable not applicable			
evaluation of safety organisation			
organisational element element existed did element relate to actual circumstances of			
yes / no no / partly / yes adequate?			
- written policy objectives No			
- specified management No			
structure			
- specified responsibilities No			
- specified working procedures No			
- specified procedures for No			
assessment/auditing of			
management system			
- specified procedures for No			
review and update of			
management policy			
- specified general training No			
procedures			
- specified emergency No			
training procedures			
evaluation of ecological impact control			
organisational element element existed did element relate to actual circumstances of			
yes / no no / partly / yes adequate?			
- ecological status review No			
before incident			
- potential ecological No			
consequences assessment			
- ecological impact review No			
after incident			
- ecological restoration No			
procedures			

-	subsequent	review	of No

restoration success

remarks - not applicable -

#### 3 Official Action Taken

#### legal action

- not applicable -

#### other official action

- not applicable -

### 4 Lessons Learned

#### measures to prevent recurrence

no information is given

#### measures to mitigate consequences:

no information is given

#### useful references:

no information is given

## 5 Discussion about Response

- not applicable -

# Appendices for the FA / 1800 121 01 report

# Appendix Full Report A / source of accident - remarks:

The accident occurred with an industrial boiler producing steam for 5 steamers (cookers). The boiler is made in the form of a cylindrical body closed with 2 flat bases (lids). The boiler comprises a focus tube and 24 exhaust gas tubes. Its capacity is 2.8 m3 and its heating surface is 25 m2. Its operating pressure is 10 bars. It can produce 1 tonne of steam per hour. The boiler has been installed in 1981, was again tested in 1990, was inspected in 1993, and was inspected again 6 days before the accident occurred, following a repair.

# Appendix Full Report B / area concerned - illustration of effects:

the map shows the points in which the boiler and its fragments were thrown

### Appendix Full Report B / area concerned - remarks:

the body of the boiler was thrown about 150 meters to the north, whereas the focus tube was thrown 200 meters to the south. A hot water tank has been found 150 meters to the south, inside a locksmith's shop.

#### Appendix Full Report B / disruption of community life:

a nearby locksmith's shop was damaged and an electrical line is cut