Utsläpp och brand på ett oljeraffinaderi då en rörledning brast.

901119 MARS 1990_17

Olyckan inträffade vid igångkörning av en enhet. En rörledning brast till följd av oklara orsaker. En brand utbröt.

Inblandade ämnen och mängder

CAS Nr. Mängd

bränsleolja okänt

Skador:

Människor: Inga. Materiella: Inga.

Miljö/ekologi: Inga effekter rapporterade.

Infrastruktur: Inga.

Erfarenheter redovisade (Ja/Nej): Nej

Report Profile

Identification of Report:

country: FA ident key: 1990 017 01

reported under Seveso I directive as major accident reports: SHORT+FULL

Date of Major Occurrence: Time of Major Occurrence

start: 1990-11-19 start: 01:05:00

finish: finish:

Establishment:

name:

address:

industry: - not applicable -

Petroleum Refinery

Seveso II status: not applicable: Yes art. 6 (notification): No

art. 7 (MAPP): No

art. 9 (safety report): No

Date of Report:

short: full:

Authority Reporting:

name:

address:

Authority Contact:

rep_cont_name:

rep_cont_phone:

rep_cont_fax:

Additional Comments: a) - not applicable b) - not applicable c) - not applicable d) - not applicable e) - not applicable -**Short Report country:** FA **ident key:** 1990_017_01 **Accident Types:** release: Yes explosion: No water contamination: No other: No fire: Yes description: A fuel oil pipeline rupture occurred during the start-up of a unit, due to severe and undue handling of the oven by high temperature and pressure. The released fuel oil was ignited resulting in a fire. **Substance(s) Directly Involved:** toxic: No explosive: Yes ecotoxic: No other: No flammable: Yes description: - Fuel Oil: amount involved = not known. **Immediate Sources of Accident:** storage: No transfer: No process: Yes other: No description: The accident occurred during the start-up of a unit in a petroleum refinery. The component involved was a fuel oil pipeline. **Suspected Causes:** plant or equipment: Yes environmental: No human: Yes other: No description: CAUSES: The accident occurred both to the malfunction of control instruments and the wrong readings of the indications. **Immediate Effects:**

material loss: Yes

human deaths: No

human injuries: No community disruption: Yes

other: No

ecological harm: No

national heritage loss: No

description:

MATERIAL LOSS:... see Appendix Short Report / description of immediate effects

Emergency Measures taken:

on-site systems: Yes decontamination: No

external services: Yes restoration: No

sheltering: No other: No

evacuation: No

description:

INSIDE THE ESTABLISHMENT:

The on-site emergency plan was activated. The external fire brigade and the authorities were alerted.

Immediate Lessons Learned:

prevention: Yes other: No

mitigation: No

description:

MEASURES TO PREVENT ANY RECURRENCE OF SIMILAR ACCIDENTS:

After the accident, the measurements range of the control instruments was modified and their correct

functioning was validated.

A Occurrence Full Report

country: FA ident key: 1990_017_01

1 Type of Accident

remarks: A fuel oil pipeline rupture (code 1102) occurred during the start-up of a

unit, due to severe and undue handling of the oven by high temperature and

pressure. The released fuel oil was ignited resulting in a fire (code 1202).

2 Dangerous Substances

remarks: No data are available about the amount of fuel oil involved in the accident.

3 Source of Accident

illustration: - not applicable -

remarks: - not applicable -

4 Meteorological Conditions

precipitation none: fog: rain: hail: snow:

No No No No No

wind speed (m/s):

direction (from):

stability (Pasquill):

ambient temperature (∞ C):

```
5 Causes of Major Occurrence
main causes
technical / physical 5105 operation: instrument/control/monitoring-device failure
- not applicable -
- not applicable -
- not applicable -
- not applicable -
human / organizational 5401 person: operator error
- not applicable -
- not applicable -
- not applicable -
- not applicable -
remarks: The accident occurred both to the malfunction of control instruments (code 5105) and the
wrong readings of the indications (code 5401).
6 Discussion about the Occurrence
- not applicable -
Type of Accident country: FA ident key: 1990_017_01
event:
major occurrence 1202 fire: pool fire (burning pool of liquid, contained or uncontained)
initiating event 1102 release: fluid release to ground
associated event - not applicable -
Dangerous substances
country: FA ident key: 1990_017_01
a) total establishment inventory
CAS number: identity: Fuel Oil
name from Seveso I Directive: - not applicable -
name from Seveso II Directive: - not applicable -
category from Seveso II: - not applicable -
other hazards (1): - not applicable -
other hazards (2): - not applicable -
maximum quantity (tonnes): -1
use of substance as: STARTING MATERIAL
b) substance belongs to relevant inventory directly involved: Yes
actual quantity: -1 potential quantity: -1
c) substance belongs to relevant inventory indirectly involved: No
```

B Consequences Full Report

actual quantity: -1 indir_pot_quant: -1

country: FA ident key: 1990_017_01 1 Area concerned affected extent of effects installation: Yes establishment: Yes off-site; local: No off-site; regional: No off-site; transboundary: No illustration of effects - not applicable remarks In the accident there is no evidence of significant effects outside the establis... see Appendix Full Report B / area concerned - remarks 2 People establishment popul. emergency personnel off-site population total at risk immediate fatalities subsequent fatalities hospitalizing injuries other serious injuries health monitoring remarks No people were injured during the accident. 3 Ecological Harm pollution/contamination/damage of:

- residential area (covered by toxic cloud) not applicable
- common wild flora/fauna (death or elimination) not applicable
- rare or protected flora/fauna (death or elimination) not applicable
- water catchment areas and supplies for consumption or recreation not applicable
- land (with known potential for long term ecological harm or not applicable

preventing human access or activities)

- marine or fresh water habitat not applicable
- areas of high conservation value or given special protection not applicable

remarks In the Original Report there is no evidence of significant ecological harms.... see Appendix

 $Full\ Report\ B\ /\ ecological\ harm$

4 National Heritage Loss

effects on:

- historical sites not applicable historic monuments not applicable
- historic buildings not applicable art treasures not applicable

remarks No data available.

5 Material Loss

establishment losses off site losses

costs (direct costs to operator) (social costs) in ECU ECU material losses response, clean up, restoration remarks The accident caused damages inside the establishment but no data are available ... see Appendix Full Report B / material loss 6 Disruption of Community Life establishment/plant evacuated disabled/unoccupiable destroyed - nearby residences/hotels No No No - nearby factories/offices/small shops No No No - schools, hospitals, institutions No No No - other places of public assembly No No No interruption of utilities etc. no / yes duration - gas No - electricity No - water No - sewage treatment works No - telecommunications No - main roads No - railways No - waterways No - air transport No significant public concern none local level national level

- off site populations No Yes No

- media interest No No No

- political interest No No No

remarks The accident had impact on public.

7 Discussion of Consequences

C Response Full Report

country: FA ident key: 1990_017_01

1 Emergency Measures

- not applicable - - not applicable -

taken - on site - not applicable - - not applicable -- not applicable - - not applicable -- not applicable - - not applicable -- off site - not applicable - - not applicable -- not applicable - - not applicable -

```
still - on site - not applicable - - not applicable -
required
- not applicable - - not applicable -
- not applicable - - not applicable -
- off site - not applicable - - not applicable -
- not applicable - - not applicable -
- not applicable - - not applicable -
continuing contamination or danger
-on site not applicable
-off site not applicable
remarks - not applicable -
2 Seveso II Duties
pre-accident evaluation
Article item not due yet not done done/submitted evaluated
6 notification No No No No
7 policy (MAPP) No No No No
9 safety report No No No No
9, 10, 11 update No No No No
11 internal plan No No No No
11 external plan No No No No
13 informing public No No No No
9, 12 siting policy No No No No
post-accident evaluation
Seveso II duty was actual were actual compared with actual
contingency consequences consequences, the
addressed? addressed? predicted extent was?
Article item
7 policy (MAPP) not applicable not applicable not applicable
9 current safety report not applicable not applicable not applicable
11 internal plan not applicable not applicable not applicable
11 external plan not applicable not applicable not applicable
13 informing public not applicable not applicable not applicable
9, 12 siting policy not applicable not applicable not applicable
evaluation of safety organisation
organisational element element existed did element relate to actual circumstances of
yes / no no / partly / yes adequate?
- written policy objectives No
- specified management No
```

structure
- specified responsibilities No
- specified working procedures No
- specified procedures for No
assessment/auditing of
management system
- specified procedures for No
review and update of
management policy
- specified general training No
procedures
- specified emergency No
training procedures
evaluation of ecological impact control
organisational element element existed did element relate to actual circumstances of
yes / no no / partly / yes adequate?
- ecological status review No
before incident
- potential ecological No
consequences assessment
- ecological impact review No
after incident
- ecological restoration No
procedures
- subsequent review of No
restoration success
remarks - not applicable -
3 Official Action Taken
legal action
- not applicable -
other official action
- not applicable -
4 Lessons Learned
measures to prevent recurrence
After the accident, the measur see Appendix Full Report C / lesson learned - prevent
measures to mitigate consequences:
- not applicable -
useful references:
- not applicable -
5 Discussion about Response
- not applicable -

Appendices for the FA / 1990_017_01 report

Appendix Short Report / description of immediate effects:

MATERIAL LOSS:

The accident caused damages inside the establishment but no data are available about the cost of the material losses.

COMMUNITY DISRUPTION:

The accident had impact on public.

Appendix Full Report B / area concerned - remarks:

In the accident there is no evidence of significant effects outside the establishment.

Appendix Full Report B / ecological harm:

In the Original Report there is no evidence of significant ecological harms.

Appendix Full Report B / material loss:

The accident caused damages inside the establishment but no data are available about the cost of the material losses.

Appendix Full Report C / lesson learned - prevent:

After the accident, the measurements range of the control instruments was modified and their correct functioning was validated.