Anlagd brand i lageryutrymme på en fabrik för produktion av pesticider.

890216 MARS 1989_01

Efter arbetstid antändes en lastpall med 2000 behållare av insektsbekämpningsmedel. Branden var anlagd. Brandlarmet gicxk och räddningstjänsten tillkallades. Ungefär 600 av behållarna (totalt 6 kg bekämpningsmedel) brann upp innan räddningstjänsten hunnit släcka branden. Befolkningen i närheten av anläggningen (upp till 55 m bort) varnades.

Inblandade ämnen och mängder

	CAS Nr.	Mängd
sulfotep (aktivt ämne i	3689-24-5	6 kg
insektsbekämpningsmedel)		

Skador:

Människor:	Inga.
Materiella:	Anläggningen skadades.
Miljö/ekologi:	Inga effekter rapporterade.
Infrastruktur:	Inga

Erfarenheter redovisade (Ja/Nej): Nej

Report Profile

Identification of Report:

country: FA ident key: 1989_001_01

reported under Seveso I directive as major accident reports: SHORT+FULL

Date of Major Occurrence: Time of Major Occurrence

start: 1989-02-16 start:

finish: finish:

Establishment:

name:

address:

industry: 2004 pesticides, pharmaceuticals, other fine chemicals

Pesticide (Filling Facilities for an Insects Disinfectant)

Seveso II status: not applicable: Yes art. 6 (notification): No

art. 7 (MAPP): No

art. 9 (safety report): No

Date of Report:

short: full:

Authority Reporting:

name:

address:

Authority Contact:

rep_cont_name:

rep_cont_phone:

rep_cont_fax:

Additional Comments:

- a) not applicable -
- b) not applicable -
- c) not applicable -
- d) not applicable -
- e) not applicable -

Short Report

country: FA ident key: 1989_001_01

Accident Types:

release: No explosion: No

water contamination: No other: No

fire: Yes

description:

ACCIDENT CASE HISTORY DESCRIPTION see Appendix Short Report / description of accident types

Substance(s) Directly Involved:

toxic: Yes explosive: Yes

ecotoxic: No other: No

flammable: Yes

description:

- Sulfotep [contained in Insects Disinfectants] (C.A.S. CODE: 3689-24-5, E.E.C. CODE: 015-027-00-3): amount

involved = 6 Kg in 600 containers with a whole capacity of 32 Kg.

Immediate Sources of Accident:

storage: Yes transfer: No

process: Yes other: No

description:

The accident occurred, outside the normal working period, in a pesticide industry and involved a pallet with

2,000 containers of the preparation (an insects disinfectants).

Suspected Causes:

plant or equipment: No environmental: Yes

human: Yes other: No

description:

CAUSES:... see Appendix Short Report / description of suspected causes

Immediate Effects:

material loss: Yes

human deaths: No

human injuries: No community disruption: Yes

other: No

ecological harm: No

national heritage loss: No

description:

MATERIAL LOSS:... see Appendix Short Report / description of immediate effects

Emergency Measures taken:

on-site systems: Yes decontamination: Yes

external services: No restoration: Yes

sheltering: Yes other: No

evacuation: No

description:

INTERNAL TO THE ESTABLISHMENT ... see Appendix Short Report / description of emergency measures taken

Immediate Lessons Learned:

prevention: No other: Yes

mitigation: No

description:

Not relevant since this facility had not been re-built.

A Occurrence Full Report

country: FA ident key: 1989_001_01

1 Type of Accident

remarks: Outside the normal working period, a pallet with 2,000 containers of the preparation (an insects disinfectant) caught fire because of arson (sabotage action). 600 containers were burnt before the fire brigade extinguished the fire (code 120... see Appendix Full Report A / type of accident

2 Dangerous Substances

remarks: The total establishment and the potential directly involved inventories of sulfotep refer to the whole amount on the pallet which caught fire (20 Kg in 2,000 containers with a whole capacity of about 107 Kg). The actual directly involved in... see Appendix Full Report A / dangerous substances

3 Source of Accident

illustration: - not applicable -

remarks: The accident occurred, outside the normal working period, in a pesticide industry (code 2004) and involved a pallet with 2,000 containers (code 4006) of the preparation (an insects disinfectants) in the filling facility (code 3401).

4 Meteorological Conditions

precipitation none: fog: rain: hail: snow:

No No No No

- wind speed (m/s):
- direction (from):
- stability (Pasquill):

ambient temperature (∞C):

remarks: - not applicable -

5 Causes of Major Occurrence

main causes

technical / physical 5206 environment: establishment safeguarding/security deficiency

- not applicable -
- not applicable -
- not applicable -
- not applicable -

human / organizational 5404 person: malicious intervention

- not applicable -
- not applicable -
- not applicable -
- not applicable -

remarks: The accident was caused by an arson [5404] (sabotage action) made possible by an

inadequate safeguarding of the installation outside the normal working period (code 5206).

6 Discussion about the Occurrence

- not applicable -

Type of Accident country: FA ident key: 1989_001_01

event:

major occurrence 1201 fire: conflagration (a general engulfment fire)

initiating event 1201 fire: conflagration (a general engulfment fire)

associated event - not applicable -

Dangerous substances

country: FA ident key: 1989_001_01

a) total establishment inventory

CAS number: 3689-24-5 identity: Sulfotep

name from Seveso I Directive: - not applicable -

name from Seveso II Directive: - not applicable -

category from Seveso II: - not applicable -

other hazards (1): - not applicable -

other hazards (2): - not applicable -

maximum quantity (tonnes): 0,02

use of substance as: NORMAL FINISHED PRODUCT

b) substance belongs to relevant inventory directly involved: Yes

actual quantity: 0,006 potential quantity: 0,02

c) substance belongs to relevant inventory indirectly involved: No

actual quantity: -1 indir_pot_quant: -1

Source of Accident - Situation country: FA ident key: 1989_001_01

situation

industry

inititating event 2004 pesticides, pharmaceuticals, other fine chemicals

associated event - not applicable -

activity/unit

major occurrence 3401 other: packaging (bagging, cylinder filling, drum filling, etc.)

inititating event 3401 other: packaging (bagging, cylinder filling, drum filling, etc.)

associated event - not applicable -

component

major occurrence 4006 free placement (unconfined pile, stack,etc; if bagged or in cylinders,

```
more...F1!)
```

inititating event 4006 free placement (unconfined pile, stack,etc; if bagged or in cylinders,

more...F1!)

associated event - not applicable -

B Consequences Full Report

country: FA ident key: 1989_001_01

1 Area concerned

affected

extent of effects installation: Yes

establishment: Yes

off-site; local: No

off-site; regional: No

off-site; transboundary: No

illustration of effects - not applicable -

remarks Even if the population within 55 metres of the establishment was warned, in the ... see Appendix

Full Report B / area concerned - remarks

2 People

establishment popul. emergency personnel off-site population

total at risk

immediate fatalities

subsequent fatalities

hospitalizing injuries

other serious injuries

health monitoring

remarks No people were injured during the accident.

3 Ecological Harm

pollution/contamination/damage of:

- residential area (covered by toxic cloud) Suspected
- common wild flora/fauna (death or elimination) Suspected
- rare or protected flora/fauna (death or elimination) Suspected
- water catchment areas and supplies for consumption or recreation Suspected
- land (with known potential for long term ecological harm or Suspected
- preventing human access or activities)
- marine or fresh water habitat Suspected
- areas of high conservation value or given special protection Suspected
- remarks In the Original Report there is no evidence of significant ecological harms.... see Appendix

Full Report B / ecological harm

4 National Heritage Loss

effects on:

- historical sites not applicable - historic monuments not applicable

- historic buildings not applicable - art treasures not applicable

remarks No data available.

5 Material Loss

establishment losses off site losses

costs (direct costs to operator) (social costs)

in ECU DM ECU DM

material losses 200000

response, clean up, restoration

remarks The fire caused damages to the building and the filling equipment. The cost of t... see Appendix

Full Report B / material loss

6 Disruption of Community Life

establishment/plant evacuated disabled/unoccupiable destroyed

- nearby residences/hotels No No No

- nearby factories/offices/small shops No No No
- schools, hospitals, institutions No No No
- other places of public assembly No No No

interruption of utilities etc. no / yes duration

- gas No

- electricity No
- water No
- sewage treatment works No
- telecommunications No

- main roads No
- railways No
- waterways No
- air transport No

significant public concern none local level national level

- off site populations No Yes No

- media interest No No No

- political interest No No No

remarks Even if the population within 55 metres of the establishment was warned, in the ... see Appendix

7 Discussion of Consequences

C Response Full Report

country: FA ident key: 1989_001_01

1 Emergency Measures

taken - on site - not applicable - - not applicable -

- not applicable - - not applicable -

- not applicable - - not applicable -

- off site - not applicable - - not applicable -

- not applicable - - not applicable -

- not applicable - - not applicable -

still - on site - not applicable - - not applicable -

required

- not applicable - - not applicable -

- not applicable - - not applicable -

- off site - not applicable - - not applicable -

- not applicable - - not applicable -

- not applicable - - not applicable -

continuing contamination or danger

-on site not applicable

-off site not applicable

remarks - not applicable -

2 Seveso II Duties

pre-accident evaluation

Article item not due yet not done done/submitted evaluated

6 notification No No No No

7 policy (MAPP) No No No No

9 safety report No No No No

9, 10, 11 update No No No No

11 internal plan No No No No 11 external plan No No No No 13 informing public No No No No 9, 12 siting policy No No No No post-accident evaluation Seveso II duty was actual were actual compared with actual contingency consequences consequences, the addressed? addressed? predicted extent was? Article item 7 policy (MAPP) not applicable not applicable not applicable 9 current safety report not applicable not applicable not applicable 11 internal plan not applicable not applicable not applicable 11 external plan not applicable not applicable not applicable 13 informing public not applicable not applicable not applicable 9, 12 siting policy not applicable not applicable not applicable evaluation of safety organisation organisational element element existed did element relate to actual circumstances of yes / no no / partly / yes adequate? - written policy objectives No - specified management No structure - specified responsibilities No - specified working procedures No - specified procedures for No assessment/auditing of management system - specified procedures for No review and update of management policy - specified general training No procedures - specified emergency No training procedures evaluation of ecological impact control organisational element element existed did element relate to actual circumstances of yes / no no / partly / yes adequate? - ecological status review No

before incident

- potential ecological No

consequences assessment

- ecological impact review No

after incident

- ecological restoration No

procedures

- subsequent review of No

restoration success

remarks - not applicable -

3 Official Action Taken

legal action

- not applicable -

other official action

- not applicable -

4 Lessons Learned

measures to prevent recurrence

Not relevant since this facili... see Appendix Full Report C / lesson learned - prevent

measures to mitigate consequences:

Not relevant since this facili... see Appendix Full Report C / lesson learned - mitigate

useful references:

- not applicable -

5 Discussion about Response

- not applicable -

Appendices for the FA / 1989_001_01 report

Appendix Short Report / description of accident types:

ACCIDENT CASE HISTORY DESCRIPTION:

Outside the normal working period, a pallet with 2,000 containers of the preparation (an insects disinfectant) caught fire because of arson (sabotage action). 600 containers were burnt before the fire brigade extinguish the fire. The population within 55 metres of the establishment was warned. Fire fighting water and contaminated soil were collected and disposed.

Appendix Short Report / description of suspected causes:

CAUSES:

The accident was caused by an arson (sabotage action) made possible by an inadequate safeguarding of the installation outside the normal working period.

Appendix Short Report / description of immediate effects:

MATERIAL LOSS:

The fire caused damages to the building and the filling equipment. The cost of the damages has been estimated in about 200,000 Deutch Marcs (about 0.1 MECU).

COMMUNITY DISRUPTION:

The population within 55 metres of the establishment was warned.

Appendix Short Report / description of emergency measures taken:

INTERNAL TO THE ESTABLISHMENT:

The fire alarm was sounded and the fire brigade intervened. Fire fighting water and contaminated soil were collected and disposed.

EXTERNAL TO THE ESTABLISHMENT:

The population within 55 metres of the establishment was warned.

Appendix Full Report A / type of accident:

Outside the normal working period, a pallet with 2,000 containers of the preparation (an insects disinfectant) caught fire because of arson (sabotage action). 600 containers were burnt before the fire brigade extinguished the fire (code 1201).

Appendix Full Report A / dangerous substances:

The total establishment and the potential directly involved inventories of sulfotep refer to the whole amount on the pallet which caught fire (20 Kg in 2,000 containers with a whole capacity of about 107 Kg). The actual directly involved inventory of sulfotep refers to the 600 containers (with a whole capacity of 32 Kg) involved in the fire.

Appendix Full Report B / area concerned - remarks:

Even if the population within 55 metres of the establishment was warned, in the Original Report there is no evidence of significant effects outside the establishment.

Appendix Full Report B / ecological harm:

In the Original Report there is no evidence of significant ecological harms.

Appendix Full Report B / material loss:

The fire caused damages to the building and the filling equipment. The cost of the damages has been estimated in about 200,000 Deutch Marcs (about 0.1 MECU).

Appendix Full Report B / disruption of community life:

Even if the population within 55 metres of the establishment was warned, in the Original Report there is no evidence of significant effects outside the establishment.

Appendix Full Report C / lesson learned - prevent:

Not relevant since this facility had not been re-built.

Appendix Full Report C / lesson learned - mitigate:

Not relevant since this facility had not been re-built.