

Gasutsläpp och explosion på kraftwerk

Start datum: 20010108

Händelse kod: DE/2001/001-[01]

Kort rapport

Typ av händelse

Explosion och utsläpp på kraftverk.

Inblandade ämnen

Seveso II ämnet kategori : högt flambar, mängd 0,0 Kg.

Olycksobjekt

Normala operationsvillkor

Olycksorsak

Det finns ingen kommentar.

Skador

De materiella skadorna (byggnader och bilar)

Akutåtgärder

- Kontroll av närliggande område för gas
- Brand bekämpningsoperation i två faser
- Att sätta sigill på skadade rör
- Rening av spillror
- Reparation av skadade byggnader
- Vägavspärrning av polis
- Förberedelse av akutskydd

Erfarenheter

Det finns ingen kommentar.

English summary

Start date: 08/01/2001

Accident code: DE/2001/001-[01]

Accident type(s)

Explosion of coke-oven gas after release in a power plant

Substance(s) directly involved

Seveso II Substance Category: highly flammable, qty: 0.0 kg

Immediate source(s) of accident

Regular operation conditions

Suspected cause(s)

No comment

Immediate effects

On-site material losses: damage to buildings, cars, plant equipment

Off-site material losses: damage to buildings, cars,

Emergency measures taken

Protective measures:

- monitoring of the neighbourhood for gas
- fire fighting operations in two phases
- sealing of the damaged pipes

Remediation measures

- cleaning up of the debris
- repair/rehabilitation of damaged buildings according to the indication of the appointed civil engineer
- repair of the power plant in agreement with the competent authorities

Protective measures by external emergency response services

- closure of neighbouring roads by police
- preparation of emergency shelters

Immediate lessons learned

No comment