

Brand på ett oljefält

Start datum:20030113

Händelse kod: US/2003/007-[01]

Kort rapport

Typ av händelse

brand

Inblandade ämnen

Spilloja transporterades till anläggning för återvinning.

Olycksobjekt

Lastbilen transporterade spilloja och den flambara ångan fattade eld i luften.

Olycksorsak

Flambar ångan bildades över de två lastbilarna och kort efter sin ankomst orsakade en blixtejd av ångan.

Skador

En död anställd av BLSR, vilken hade skött en tank från lagring faciliteter på Caldwell Ranch på ett oljefält.

Akutåtgärder

Räddningstjänsten var på plats.

Erfarenheter

Lastbilens motor var igång och detta orsakade att flambar ånga antändes.

English summary

Start date: 13/01/2003

Accident code: US/2003/007-[01]

Accident type(s)

Flash fire.

Substance(s) directly involved

Waste oil brought to facility for disposal.

Immediate source(s) of accident

Trucks transporting waste oil may have ignited flammable vapor in air.

Suspected cause(s)

Suspect flammable cloud formed over the two tank trucks shortly after their arrival at the site, causing a #deflagration# or flash fire of the vapor.

Immediate effects

The dead were employees of BLSR, which operates a tank farm storage facility on Caldwell Ranch in an oilfield.

Emergency measures taken

Fire fighters responded.

Immediate lessons learned

The truck engine was running and may have caused the flammable vapor to ignite.